


# mini-module characterization

2 mini-pT modules exist

results presented last systems meeting (June 18<sup>th</sup>) showed:

lower noise & faster signals from upper sensor  
higher noise, slower signals from lower sensor  
=> higher capacitance  
results mainly from module #2



since then:


have made a study of both modules looking in more depth at effect of sensor bias  
have made some progress in understanding origins of bad channels  
have had one interim Vidyo meeting - 26<sup>th</sup> July  
actions (for me) from that meeting now complete  
(some results already circulated by e-mail)

not much new today - will use today to draw all information together in one talk  
(not everyone participated in interim meeting)

re-cap slides from last time (June 18<sup>th</sup>)

## mini-module test setup


June 18<sup>th</sup>



# channel to strip no. mapping

2 edge channels on each sensor not bonded  
(i.e. strips 2 - 255 inclusive bonded)

**main point to note: lower and upper sensor layer channels feed alternating channels on each chip**



*chip channel vs. sensor strip #*

	chip A												chip B											
	2 4 6 8 ..... 250 252 254												2 4 6 .... 248 250 252 254											
upper sensor	255 254 253 252 ..... 131 130 129												128 127 126 ... 5 4 3 2											
	chip A												chip B											
	1 3 5 7 ..... 249 251 253												1 3 5 .... 247 249 251 253											
lower sensor	2 3 4 5 ... 126 127 128												129 130 131 ... 252 253 254 255											



## s-curves

acquired using on-chip test pulse

2 clear families corresponding to  
**odd** & **even** chip channel numbers


odd CBC channels show more “stretched  
out” s-curves  
=> higher noise

odd channels correspond to lower sensor



# noise measurements: module #2, 300V bias

June 18<sup>th</sup>  
electrons  
(approx.)



higher noise from lower sensor channels  
not clear why


no explanation for anomalously low noise channels either  
would seem to indicate no sensor-to-hybrid contact

← NO - see later



# test pulse charge injection time sweep

June 18<sup>th</sup>



slower edge times for odd channels (lower sensor) => slower pulse shape => higher capacitance

consistent with higher noise

seems to indicate lower sensor not properly depleted? ← NO - see later

note: other module not studied in such depth  
but shows broadly similar results ← bit different - see later  
significant?

## conclusions from June 18 meeting

sensor behaviour on modules not clearly understood

results presented for 300V bias

suggestion to vary bias over wider range - might shed some light



# recap slides from Vidyo meeting- 26/7/13



study of both modules looking in more depth at effect of sensor bias

progress in understanding origins of bad channels


# noise vs. sensor bias: experimental method

- tune offsets for all channels to centre s-curve mid-points at same value (150) for test pulse amplitude  $\sim 1$  fC
- s-curves acquired by sweeping global comparator threshold parameter VCTH
- fit to s-curve raw data allows noise to be extracted (rms VCTH I2C units)

example result from module #1, 50V bias



# sorting the noise



alternating high/low noise values  
=> one sensor (lower one) giving  
consistently higher noise than other

also a significant number of low  
noise channels

if sort chip channels by sensor with which  
they are associated, then systematic  
difference between each  
sensor becomes clearer

for this module (#1), at **50V**  
bias, the lower sensor  
channels show higher noise

# leakage behaviour for both modules

**mini-module#1**

bias [V]	leakage [ $\mu$ A]
20	1.02
50	2.6
100	6.1
200	16.4
300	35
400	60

**mini-module#2**

bias [V]	leakage [ $\mu$ A]
50	0.28
100	0.56
200	1.3
300	2.5
400	5.6
500	13.8
600	39.3

tables show leakage (both sensors) dependence on bias

bias voltage taken to a level where noisy channels start to appear


will only show noise sorted by sensor , for each module

note: one chip only now working on module#2. CBC2B got damaged when probing sensor to verify bias voltage getting through to strips (not sure how it happened)

mini-module#1: **upper** sensor

some scratches in  
this area, also  
looks like 1 broken  
bond wire


noise performance vs bias => **capacitance**  
seen by chip already close to **lowest** value  
at 20V bias





broken wire



on 2<sup>nd</sup> channel  
- could be touching bias line





# surface scratches


but **not** so obvious correlation with  
problem channels  
(previously thought there was)






## mini-module#1: **lower** sensor


sorting noise data by sensor strip number: lower sensor, 20 & **50V**




## mini-module#1: **lower** sensor




## mini-module#1: **lower** sensor



## mini-module#1: **lower** sensor




## mini-module#1: **lower** sensor



# comparison of two sensors on mini-module#1


Vbias: 20 - 400 V



lower sensor noise needs higher bias (>100V) before reaching minimum value

but final levels ~same - lower and upper (slightly higher on lower)

## comparison of two sensors on mini-module#2



similar behaviour, but lower sensor doesn't get to as low levels as upper before noisy strips start to develop



## summary so far

### observations from bias studies - both modules

different dependence of noise on bias

for both modules the lower sensor needs higher bias

is this is just a coincidence?

← my preference

(i.e. not related to some kind of effect of the hybrid)


or something related to the hybrid

cannot see what this could be

low-noise channels are not affected by the sensor bias - would seem to indicate that they are not connected - but where?

next few slides will show evidence that failure looks to be at the bump-bond level

# investigating low-noise module channels




behaviour observed consistent with failure of connection between strip and amplifier  
poor wire contact? something wrong with sensor?  
failed bump-bond seems the most likely?

if can place grounded probe on wire-bond pad on hybrid then can switch off input transistor and channel will no longer respond to test pulse


if bump-bond has failed then channel will still respond to test pulse

# makeshift probing arrangement





a bit closer in





# view through microscope



can't get  
to these  
bond  
pads

can get to every other  
bond pad with probe  
needle

probe needle



probe needle  
shadow

## module under study: module#2(chip A only)





gain plot shows s-curve mid-points resulting from  $\sim 1fC$  test pulse  
(after tuning comparator offsets to value of 150)

will concentrate on region around these two “bad” strips



now place grounded probe on strip 50 wire-bond pad



for a normally behaving channel (strip 50), grounding the wire-bond pad which is connected (via bump-bond) to CBC input, means that that channel no longer responds to the test-pulse

amplitude (strip 50) drops to pedestal level  $\sim 130$


noise of that channel also drops

not to zero, but possibly noise introduced by the probe passes through the preamp feedback capacitor  $C_f$

now proceed to “walk” grounded probe along the strips - remember can only safely probe every other strip



## grounding every other strip - one at a time



strip 56 still responds to the test pulse

implication is that strip 56  
(one of the two “bad” channels)  
is disconnected from the wire-  
bond pad

presumably the bump-bond has failed?

## further investigations

results up-to-here discussed during Vidyo meeting (26<sup>th</sup> July)


- noise measurements for lower sensors on both modules still a puzzle -  
are they depleting as expected from previous measurements on sensors?  
(before module assembly)

=> check signal amplitude vs. bias - not just noise

- can we be sure low noise channels due to bump-bond failure?  
could be due to cracked track (metallization for bonding makes tracks more brittle)

=> probe faulty channel closer to chip after scraping off solder mask

## signal vs. bias - mini-module#1



### method:


threshold set at  $\sim 1$  fC, Sr-90 source

look at one channel from each layer in middle of area “illuminated” by source

count number of times comparator fires for 100,000 scintillator triggers

counts saturate as bias voltage approaches 250 Volts

## signal vs. bias - mini-module#2



similar result


probing  
further  
along  
track

coating scratched  
off via and probed  
- still no contact  
with amp input

=> discontinuity must  
be beyond this point




## what about very low noise channels?




this one corresponds to the broken wire - what about the others?

to diagnose look at test pulse response behaviour

## varying test pulse amplitude: **UPPER** sensor




high noise channels show reduced response to test pulse  
symptomatic of shorted channel response  
(verified on electrical test setup)




very low noise channels show no response to test pulse  
damaged amplifiers? or shorted to something?



## varying test pulse amplitude: **LOWER** sensor



one high noise channels showing reduced response to test pulse  
could be shorted to neighbour channel on chip but other sensors  
(see previous slide)



pair of very low noise channels on this sensor also showing no response to test pulse

## overall summary

- signal measurements show sensor appears to be depleting as expected
- still no explanation for noise dependence on bias for lower layer sensors
  - different inter-strip capacitance dependence on bias for these sensors?
    - (note: both sensors don't behave in quite the same way)
    - or some effect due to the hybrid?
- low noise channels are disconnected from amplifiers - evidence points to the bump-bonds disconnection during the module assembly/wire-bonding process?
- very low noise channels show no response to test pulse
  - damaged or shorted somewhere/somehow?
- high noise (low-gain) channels (not those bias related) appear to be shorted
  - but weren't there prior to module assembly (gain measured for all channels)

## next step


make another module - use hybrid with under-filled chips

should not be possible to disturb bump-bonds

use hybrid where wire-pad to amplifier connectivity has been verified for all channels

# testing all channels on a hybrid

cycle test pulse continuously through all chip channels  
view chip output frames on scope - infinite persistence  
lower grounded probe tip on wire-bond pad - signal should disappear for that channel  
repeat for all channels



**underfilled hybrid #U03**

all channels verified connected

both chips

top **and** bottom  
side wire bond pads  
arrays

# hybrid status summary

(those that have passed through Imp. College)

1<sup>st</sup> batch of 5 (all not under-filled)

- #1 in electrical test setup at IC
- #2 to Bristol for first tests with FMC, now passed on to Strasbourg
- #3 problem with I2C lines disconnected at connector - repaired - keep at IC
- #4 -> mini-module #1
- #5 -> mini-module #2

2<sup>nd</sup> batch: 4 under-filled, 2 not

- N01 at IC
- N02 at IC
- U01 at IC
- U03 at IC
- U04 -> Bristol for FMC development (will come back with FMC to IC)
- U06 all channels probed, to CERN for another mini-module